#### REVERSE AUCTION PROGRAM

# **Uniform Physical Condition Standards (UPCS) Inspection Services BUSINESS RULES**

Effective November 17, 2004

This document identifies the Business Rules for contractors interested in participating in the U.S. Department of Housing and Urban Development (HUD) Office of Public and Indian Housing (PIH) Real Estate Assessment Center (REAC) Reverse Auction Program. These rules consist of prerequisites, requirements, and policies that are subject to change. Contractors are required to access the auction website to bid on posted inspections and schedule inspections as awarded by PIH-REAC. Qualified Reverse Auction Program inspectors are required to participate in training courses, perform quality inspections in accordance with the UPCS protocol, and comply with Inspector Administration standards of conduct.

The auction bid price shall include all costs associated with the performance of the inspection. Reverse Auction contractors will not be provided additional compensation for participation in the training and bidding process, and scheduling and completion of inspections. Contractors shall refer to the Reverse Auction Program Purchase Order Terms and Conditions for specific payment terms.

Reverse auction program participants, whether small business firms or individuals, are referred to herein as contractors.

### 1.0 Reverse Auction Program Prerequisites

In order to participate in the Reverse Auction Program and access the auction website, contractors must meet the following requirements:

- Ensure that all inspectors<sup>1</sup> are certified in the UPCS inspection protocol and the current version of the Data Collection Device (DCD) software;
- Maintain a minimum of \$500,000 general liability insurance; and
- Maintain status as a Level 2, on-line service MasterCard vendor, and provide proof to PIH-REAC.

Participation in the Reverse Auction Program is limited to small businesses that meet the small business size standard for the North American Industry Classification System (NAICS) code 541350, which is \$6 million.

1

<sup>&</sup>lt;sup>1</sup> "Inspector" is defined as the individual, certified by PIH-REAC in the UPCS inspection protocol, who performs on-site property inspections. Inspectors may be contractors, employees of a contractor, subcontractors (at any tier) to a contractor, or employees of a subcontractor.

#### 1.1 Credit Card Vendor

Each contractor must establish and maintain a vendor account with a MasterCard credit card company in order to receive payment for the services provided. HUD will *not* pay the transaction or activation fees associated with establishing this vendor account or any credit card fees. If the contractor does not already have a vendor account, the contractor shall establish a vendor account with a merchant processor that provides the ability to electronically process MasterCard Purchasing Card transactions.

The contractor and merchant processor must have the ability to enter and pass Level 2 data (POS/Customer Code) to the issuing bank. The merchant processor terminal must be designated with a Merchant Category Code (MCC) of 9399-Government Services in order to permit payments to be authorized and settled. PIH-REAC requires proof of this relationship before a contractor may participate in the Reverse Auction Program. If the contractor does not remain a MasterCard vendor, the contractor *cannot* receive compensation for inspection work.

PIH-REAC will provide each contractor with an authorization number, necessary for payment, upon acceptance of the inspection product. Payment for inspections performed will be deposited directly to the responsible contractor's designated bank account.

# 2.0 Reverse Auction Program Requirements

Contractors who meet the prerequisites outlined in Section 1.0 must provide current contact information, and maintain the necessary hardware and software requirements. Inspectors must maintain active UPCS inspector certifications, and comply with Inspector Administration business rules. If the contractor employs inspectors to conduct PIH-REAC inspections, the contractor must provide inspectors that are certified by PIH-REAC in the UPCS inspection protocol. In such cases, the contractor retains the responsibility of prime contractor.

#### 2.1 Active Certification

In order to maintain active UPCS certification, inspectors must successfully perform a UPCS inspection at least once in a 180 consecutive calendar day period. A UPCS inspection is considered successful only after the inspection results have been uploaded by the inspector and accepted by PIH-REAC. Inspector Notice No. 2002-01, Maintaining Active Certification, and any additional related notices, provide further information regarding the requirement to maintain active certification.

# 2.2 Inspector Administration

Inspector Notice No. 2002-02, Inspector Administration Business Rules, and any additional related notices, outline the administrative actions that may be taken if an inspector's performance is found to be deficient. Inspector Administration also investigates trends in inspector behavior, such as frequent inspection cancellations. Certain violations of the UPCS inspection protocol may disqualify the inspector from performing future inspection services. These violations include:

- Purposeful violations and/or omissions of the inspection protocol;
- Fraud:
- Sexual or other harassment;
- Theft; and
- Violent acts.

# 3.0 <u>Contractor Training</u>

Reverse Auction contractors must participate in training activities prior to commencement of the auction, to include an online session in the use of the auction website. HUD approximates that the conference call, course(s), and/or mock auction should take each contractor a maximum of four hours to complete.

### 4.0 Reverse Auction Activities

PIH-REAC plans to conduct auctions at least once every quarter, and as frequently as twice a month. The Reverse Auction Program allows PIH-REAC to post inspections to a website, and contractors to bid on desirable properties.

#### 4.1 Program Announcement

Reverse Auction contractors will receive email notification of each upcoming auction event, to include the:

- Total number of properties in the auction event;
- Amount of time the auction will remain open for bidding; and
- Period during which the inspections must be scheduled.

# 4.2 Website Access and Help Desk Assistance

The auction website vendor will provide each Reverse Auction contractor with login credentials to access the secure auction website. If the contractor has any problems with the supplied user ID and password, the contractor may contact the current website vendor's help desk. The help desk will be staffed Monday through Friday, from 9:00 a.m. to 9:00 p.m. Eastern Time.

Contractors will be furnished with points of contact, and the corresponding email addresses and telephone numbers, for the help desk and other Reverse Auction Program assistants.

# 4.3 Property Search

When possible, the properties available for auction will be posted to the website prior to the start of the auction event. Reverse Auction contractors may use this opportunity to identify the properties on which they would like to place bids. The online system will allow each contractor, referred to as a "bidder," to search through the property inspections posted for auction using the following criteria:

- Property ID;
- Property name;
- City:
- State;
- Zip code:
- Scattered site indicator;
- Building and unit counts;
- Estimated inspection duration;
- Required date of performance; and
- Lot auction.

#### 4.4 Lot Auctions

"Lot auction" refers to a group of inspections clustered by PIH-REAC for award to a single bidder. If a bidder elects to bid on an inspection for any property in a lot, the bidder must bid on every property in that lot. If a bidder fails to bid on every property in the lot, the system will not accept the proposed bid. The eligible bidder offering to perform the lot auction for the lowest total price will be awarded the inspection work.

Each inspection within the lot remains distinct. The winning bidder will schedule each inspection separately, and the inspector will conduct each inspection separately. PIH-REAC will pay the contractor directly and separately for each accepted inspection. Failure to perform all work assigned may exempt the contractor from future inspection services.

#### 4.5 Bid Considerations

Contractors shall account for all costs and risks when determining the bid price. For example, the bidder should take into consideration the expected level of effort required to perform the inspection, as well as any related expenses, such as travel. Contractors should consider the possibility of uninspectable properties and unsuccessful inspections, and adjust their prices accordingly. In the last year, 143 of 14,031 properties were verified as unsuccessful inspections.

Contractors should also consider that the inspection fieldwork must be completed within the timeframe established by PIH-REAC, and according to the schedule agreed upon with the property representative. All aspects of the UPCS inspection protocol are expected to be followed, including: correctly documenting the property profile; accomplishing a complete verification of the property prior to generating the sample; and observing all items and recording all deficiencies correctly. Strict adherence to the protocol is necessary, as PIH-REAC is expecting high quality inspections as a result of the Reverse Auction Program.

### 4.6 Bidding Guidelines

After choosing the property inspections the contractor desires to perform, the contractor is required to submit a separate bid for each property inspection, including lot auction inspections. The website will display a maximum bid and a minimum bid for each inspection. Contractors may currently place bids in five-dollar decrements, starting at the maximum bid. If an auction reaches its minimum bid, contractors may continue to place bids, in case the original low bidder becomes ineligible. Bidders may not withdraw a bid once it has been accepted by the system.

# 4.7 Proxy Bidding

The Reverse Auction Program auction website will include a proxy bid utility, for use by the contractors at their discretion. The proxy bid utility enables a contractor to enter successive bids for property inspections, even when not logged on to the auction website. Utilizing the proxy capability, the contractor may choose an initial bid for a property and a floor price that the contractor is not willing to bid below. *The proxy functionality will not allow a floor price that is lower than the minimum bid set by PIH-REAC*. Once an initial bid is entered, the proxy bid utility will place successive bids at the next available bid price each time another bidder enters a lower bid, until it reaches the contractor's set floor price. Thus, Reverse Auction contractors do not need to be at their computer during the auction event to be competitive.

For example, suppose an auction starts at an opening price of \$500. Bidder A enters a proxy bid minimum of \$400. Bidder B subsequently enters a bid of \$450. The proxy automatically enters a lower bid at the next decrement for a bid of \$445 on behalf of Bidder A. Bidder B then enters a bid of \$400. The proxy will not enter another bid for Bidder A, since his/her floor price has been reached. However, Bidder A may continue to manually enter lower bids until the auction closes, or set up a lower proxy bid.

#### 4.8 Bid Award

PIH-REAC will award a purchase order for an individual inspection or lot of inspections to the lowest eligible bidder. If the lowest bidder is ineligible to receive the award, PIH-REAC may award the purchase order to the next lowest bidder or re-post the inspection(s) in a future auction. In the case of tie bids, the award will be made to the first bid recorded as determined by the auction software.

Following PIH-REAC's selection of the successful bidder, award notification will be made electronically. This award notification will include the following information for each inspection awarded, at a minimum:

- Winning bidder's information;
- Amount of winning bid;
- Estimated inspection days;
- Expected completion date; and
- Purchase order.

Contractors must contact PIH-REAC immediately if information in the award notification is incorrect. Once the award notification is sent, the successful bidder must obtain the property point of contact information from the PIH-REAC website. This information shall be used to schedule inspections.

### 5.0 Quality Assurance

#### 5.1 Quality Assurance Reviews

PIH-REAC also performs various on-site Quality Assurance (QA) reviews including, but not limited to, Collaborative Quality Assurance (CQA) reviews and Limited Quality Assurance (LQA) reviews. These QA reviews may be conducted at any time, including during the course of a property inspection, following an inspection, or as a separate analysis. The QA reviewer may or may not identify him/herself to the inspector during the review.

#### **5.2** Inspection Verifications

PIH-REAC may require that its personnel accompany newly certified inspectors on their first inspection to verify their understanding and compliance with the requirements of the purchase order. Depending upon the success of the inspector's first inspection, PIH-REAC may require similar oversight on subsequent inspections. PIH-REAC will notify the contractor if subsequent accompanied inspections are needed.

# 6.0 Purchase Order and Payment

HUD will not issue any paper purchase orders under this Reverse Auction Program. Contractors shall refer to the Reverse Auction Program Purchase Order Terms and Conditions for specific payment terms. The terms and conditions governing purchase orders are posted to the PIH-REAC website, and will be available via the auction website. All payments will be made using the Government wide Commercial Purchase Card (see Section 1.1).

# 7.0 Attachments

The following pages include two attachments, as referenced:

- Attachment 1 POA/ED Inspection Confirmation Text; and
- Attachment 2 Notification of Exigent and Fire Safety Hazards Observed Form.

# **Required Email Text for Inspection Confirmation**

Subject Line: Physical Inspection of [insert property name and property ID]

Name of Property Owner Property Name Property Address City, State Inspection #, Property ID

Dear [name of property owner]:

This confirms that the referenced property is scheduled for inspection beginning at [time] on [date], through [time] on [date]. Please note that the inspection will not include weekends or [insert any Federal holiday falling during the inspection period]. If there is any delay, I will immediately contact you by telephone and we will set new dates, if necessary.

Please provide the required written notice of the inspection to your residents. It is not necessary for the tenants of units selected for inspection to be present during this inspection.

Please note that your representative must accompany me at all times while he/she is on site. Your representative should be prepared to provide access to all units identified in the inspection (when the tenant is not present or the unit is vacant) and all other areas of the property (e.g., maintenance facilities, offices, etc.). I will inform your representative of the units that have been selected for inspection on the day of the inspection, which is the result of a sample drawn on-site.

The inspection will include the entire property: project grounds, common areas, office, maintenance work areas, laundry rooms, community room, etc., and a sample of buildings and units selected at random. On the day of the inspection I will verify data provided on the property profile, as per our previous discussion. Please have available the following information to assist with the verification:

- Total number of buildings and number of units within each building;
- The unique building identifier (i.e., the address or some other identifier that will enable the identification of each building for future inspections);
- All applicable certifications, including inspections of elevators, sprinkler systems, fire alarms, and boilers; lead-based paint testing certification and HUD's disclosure form (Disclosure of Information on Lead-Based Paint and/or Lead-Based Paint Hazards) for housing built prior to 1978 (including elderly properties) are also required;
- Current rent-roll (used for reference only, rent amounts are not necessary);
- Site-map or plot plan showing property layout and building locations, if available;
- Total square footage of the Parking Lots/Driveways/Roads and Walkways/Steps; if you do
  not provide these area measurements at the time of the inspection, I will provide an estimate
  of the square footages to HUD;

- Current occupancy percentage rate; and
- Copy of written notification to the residents of the inspection.

Please be advised that the terms of my contract with HUD do not permit me to discuss with you or your representative, or provide advice on, any deficiencies observed and recorded during the inspection. Both HUD and I appreciate that you may have different views regarding the deficiency definitions, but I must classify deficiencies in accordance with HUD's established inspection protocol and my best judgment. Differences of opinion regarding the facts of the inspection may be discussed with HUD staff at a later date.

HUD's Offices of Housing and Public Housing require that all exigent health and safety hazards be mitigated immediately. An exigent hazard is one that poses an immediate threat to life, health or property. During the inspection, the inspector will record all health and safety hazards. Before leaving the property, I will provide your representative with a written list of all such health and safety hazards and ask your representative to sign the form to acknowledge receipt. Such signature only acknowledges receipt of the form and does not indicate the representative's or your concurrence with its contents. A HUD representative will contact you later to assure that such items have been addressed in a timely manner.

Be advised that HUD may conduct a Quality Assurance (QA) inspection to verify the results of this inspection. That QA inspection may occur during, or shortly after this inspection.

Please reply to this email message to confirm receipt. If you have additional questions, please contact me by email or at [insert phone number].

I wish to thank you and your staff in advance for your help with this inspection.

Sincerely, Contractor Name – PIH-REAC Inspector #

cc: Dudley Ives, PIH-REAC Physical Inspection Program

# NOTIFICATION OF EXIGENT AND FIRE SAFETY HAZARDS OBSERVED

Proper	ty ID #:						Inspecti	ion ID#	Inspection Date:		
Property name:							PHA Na	ıme	Property Phone:		
Property Address:							PHA ID	Number	Agent Phone:		
Proper	ty City:		State:		Zip:						
	.,,		_					RT 1	FTV HAZARDS		
Air Quality A Propane/Natural Gas/Methane Gas Detected  Electrical Hazards B Exposed Wires/Open Panels C Water Leaks On or Near Electrical Equipment  ** The Offices of Housing and Public Housing requires							Emergency Equipment/Fire Exits/Fire Escapes D Emergency/Fire Exits/Blocked/Unusable Fire Escapes E Blocked Egress/Ladders  Gas/Oil Hot Water Heater/Gas/Oil HVAC F Carbon Monoxide Hazard - Gas/Oil Fired Unit -Missing/Misaligned Chimney  re all exigent hazards be mitigated immediately. The office of Housing requires a 72 hours of the date of the inspection. All public housing agencies are required to				
documen	t activities	in this area	a under	both PH	MAP aı	nd PHA	S require	ements	for later evaluation by HUD.		
During this  Item Number	Item Site or DU or CHECK DEFECT TYPE(s) (							and Safe	ty hazards that require immediate attention. Use additional sheets if nee  COMMENT(s)	eded.	
			A	В	С	D	E	F	Certificate <sup>2</sup>	***	
2											
3											
4											
5 *** Pasano	d for HUD Use										
Reserve	d for FIOD Ose	J.									
						E		RT 2	ZADN		
G Win	ency Equipr ndow Securit Extinguishe	y Bars Preve			<b>;</b>	<u>F</u> )	<u>PA</u> IRE SAFE	TY HAZ	ZARD  ke Detectors issing/Inoperative		
G Win H Fire	ndow Securit Extinguishe	y Bars Preve ers Expired	ent Egres	ss			IRE SAFE	Smo I M	ke Detectors		
G Win H Fire	ndow Securit Extinguishe	y Bars Preve ers Expired	ent Egres	observed	and noted	l as Fire S	IRE SAFE	Smo I M	ke Detectors issing/Inoperative		
G Win H Fire During this Item Number	ndow Securit Extinguisher inspection the Site or Bldg.	y Bars Prevers Expired e following it  DU or CA	ent Egres	observed	and noted	l as Fire S	IRE SAFE	Smo I M	ke Detectors issing/Inoperative require immediate attention:	***	
G Win H Fire  During this  Item Number	ndow Securit Extinguisher inspection the Site or Bldg.	y Bars Prevers Expired e following it  DU or CA	ent Egres	observed	and noted	l as Fire S	IRE SAFE	Smo I M	Re Detectors issing/Inoperative  require immediate attention:  MENT(s)	***	
G Win H Fire  During this  Item Number	ndow Securit Extinguisher inspection the Site or Bldg.	y Bars Prevers Expired e following it  DU or CA	ent Egres	observed	and noted	l as Fire S	IRE SAFE	Smo I M	Re Detectors issing/Inoperative  require immediate attention:  MENT(s)	***	
G Win H Fire During this  Item Number  1 2 3	ndow Securit Extinguisher inspection the Site or Bldg.	y Bars Prevers Expired e following it  DU or  CA  Location	ent Egres	observed	and noted	l as Fire S	IRE SAFE	Smo I M	Re Detectors issing/Inoperative  require immediate attention:  MENT(s)	***	
G Win H Fire During this  Item Number  1 2 3 **** Reserve	extinguished inspection the Site or Bldg. Location	y Bars Prevers Expired e following it  DU or CA Location	ent Egres ems were CHECK	observed  A DEFEC	and noted T TYPE(	l as Fire S	IRE SAFE	Smo I M	Re Detectors issing/Inoperative  require immediate attention:  MENT(s)	***	
G Win H Fire During this  Item Number  1 2 3 *** Reserve Other Healt 1.	indow Securitive Extinguisher inspection the Site or Bldg. Location	y Bars Prevers Expired e following it  DU or CA Location	ent Egres ems were CHECK	observed  A DEFEC	and noted T TYPE(	l as Fire S	IRE SAFE	Smo I M	Re Detectors issing/Inoperative  require immediate attention:  MENT(s)	***	
G Win H Fire During this  Item Number  1 2 3 *** Reserve Other Healt	indow Securitive Extinguisher inspection the Site or Bldg. Location	y Bars Prevers Expired e following it  DU or CA Location	ent Egres ems were CHECK	observed  A DEFEC	and noted T TYPE(	l as Fire S	IRE SAFE	Smo I M	Re Detectors issing/Inoperative  require immediate attention:  MENT(s)	***	
G Win H Fire  During this  Item Number  1 2 3  *** Reserve  Other Healt 1. 2	indow Securitive Extinguisher inspection the Site or Bldg. Location	y Bars Prevers Expired e following it  DU or CA Location  c.	ems were CHECH G	observed  K DEFEC	and noted T TYPE( H  Matrix.	d as Fire S	IRE SAFE	Smo I M	Re Detectors issing/Inoperative  require immediate attention:  MENT(s)	***	
G Win H Fire During this  Item Number  1 2 3 *** Reserve Other Healt 1. 2 NAME OF	e Extinguisher Extinguisher Inspection th Site or Bldg. Location  d for HUD Use th and Safety	y Bars Prevers Expired e following it  DU or CA Location  Concerns No	ems were CHECH G t Defined	observed  A DEFEC  In Above	and noted T TYPE( H  Matrix.	d as Fire S	Gafety haza	Smo I M	Re Detectors issing/Inoperative  In require immediate attention:  MENT(s)  Certificate	***	

A copy of this notification will be provided to the appropriate local health/safety/fire code enforcement entity.

Neither the inspector's employer nor the Department of Housing and Urban Development assume any liability whatsoever expressed or implied that the above noted health and safety hazards constitute all of the health and safety deficiencies that may be present on the property. Any and all liability for the health and safety hazards noted above, as well as any health and safety hazards that my exist on the property but were not observed by the inspector, are the full and absolute responsibility of the property owner and not the inspector's employer nor the Department of Housing and Urban Development.

# NOTIFICATION OF EXIGENT AND FIRE SAFETY HAZARDS OBSERVED (continued)

Inspection ID #

Inspection Date:

Inspector ID #	PART 1
EXIGENT I	HEALTH AND SAFETY HAZARDS
Air Quality	Emergency Equipment/Fire Exits/Fire Escapes
A Propane/Natural Gas/Methane Gas Detected	D Emergency/Fire Exits/Blocked/Unusable Fire Escapes
	E Blocked Egress/Ladders
Electrical Hazards	
B Exposed Wires/Open Panels	Gas/Oil Hot Water Heater/Gas/Oil HVAC
C Water Leaks On or Near Electrical Equipment	F Carbon Monovide Hazard - Gas/Oil Fired Unit -Missing/Misaligned

During this inspection, the following items were observed and noted as Exigent Health and Safety hazards that require immediate attention. Use additional sheets if needed.

Item Number	Site or Bldg. Location	DU or CA Location	CHECK DEFECT TYPE(s) (See list below)						COMMENT(s)	
			A	В	C	D	E	F	Certificate**	
6.										
7.										
8.										
9.										
10.										
11.										
12.										
13										
14.										
15.										
14. 15. 16.										
17.										
18. 19.										
19.										
20. 21.										
21.										
22.										
22. 23.										
24.										
24. 25. 26. 27. 28. 29.										
26.										
27.										
28.										
29.										
30										
31. 32. 33.										
32.										
33.										
34.										
35.										
36.			1							
37.			1							
38.										
35. 36. 37. 38. 39. 40.			1	1						
40.			1	1						
41.			1	1						
42										
42. 43.			1							
44.			<del>                                     </del>	1			<del>                                     </del>			
45.			<del>                                     </del>	<b> </b>			<b>-</b>			

<sup>\*\*\*</sup> Reserved for HUD Use.

Property ID #:

<sup>\*\*</sup> The Offices of Housing and Public Housing require all exigent hazards be mitigated immediately. The office of Housing requires a written report to be filed with the local office within 72 hours of the date of the inspection. All public housing agencies are required to document activities in this area under both PHMAP and PHAS requirements for later evaluation by HUD.

# NOTIFICATION OF EXIGENT AND FIRE SAFETY HAZARDS OBSERVED (continued)

Property ID #: Inspection	ID # Inspection Date:
Inspector ID #	
<u></u> <u>P</u>	ART 2
FIRE SAF	ETY HAZARD
Emergency Equipment/Fire Exits/Fire Escapes	Smoke Detectors
G Window Security Bars Prevent Egress	I Missing/Inoperative
H Fire Extinguishers Expired	

During this inspection the following items were observed and noted as Fire Safety hazards which require immediate attention:

Item Number	Site or Bldg. Location	DU or CA Location	CHECK DEFECT TYPE(s) (See list below)					
			G	Н	I		Certificate***	
4.								
5.								
6.								
7.								
8.								
9.								
10.								
11.								
12.								
13.								
14.							-	
15.								
16. 17.								
1/.			-				1	
18.			-					
19.								
20.								
21. 22.								
22.								
23.								
24. 25.								
26.								
27.								
20.								
28. 29.								
30								
30. 31.								
32.								
33.								
34.			1					
34. 35.			1					
36.								
37.								
38.								
39.								
39. 40.								
41.								
42.								
43.								
44.								
45.								
46. 47.								
47.								
48.								
49. 50.		_						
50.								

<sup>\*\*\*</sup> Reserved for HUD Use.